

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/4/8	MAKE	CAT	MODEL	330DL
SERIAL	CAT0330DVRDK00172		STAMP	CAT0330DVRDK00172	
HR METER	UNKNOWN	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE	SHOE		700G	

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
MAIN PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	
Glasses	<u>FAIR</u> · Attn	
AirCon	<u>A/C</u> · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> · Attn	セパレートブーム SEPARATE BOOM
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · Attn	
Arm Cylinder	<u>FAIR</u> · Attn	
ATTACHMENT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
バックモニター画面故障あり BACK MONITOR: MALFUNCTION モニターから「ピー」の音が鳴りっぱなし、赤ランプ点滅している WARNING DOUNDS: ON, RED LAMP AT MONITOR: BLINKED モニターに自動停止キャンセル表示出っぱなし "AUTO SHUT-OFF CANCEL" MESSAGE DISPLAY E-フェンスバックアップ、E-フェンス干渉表示あり WARNINGS DISPLAY FOR 2D E-FENCE BACKUP & CAB AVOIDANCE アタッチメントなし WITHOUT ATTACHMENT 付属品:3段ブーム(四街道ヤードにあり) 3-SECTION BOOM AS SPARE (@YOTSUKAIDO YARD)	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	YES · <u>NO</u>
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u>
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。