

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/4/8	MAKE	MAEDA	MODEL	HF090-3
SERIAL No.	PLATE : 9HF3150		STAMP : NU0930150		
HR METER	4728	HR	Odometer	-	km
YEAR					YR
CHASSIS	MODEL -		No. -		
SHOE	300R		TIRE SIZE		
MAX HIGHT	9.1	m		MAX WEIGHT	200 kg

ENGINE : MODEL S/N	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	YES <input checked="" type="radio"/> NO
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	AT · MT No. OF GEARS - GEARS
Transmission	<input checked="" type="radio"/> FAIR · Attn
4WD	4WD · 2WD
Travel	<input checked="" type="radio"/> FAIR · Attn
Swing	<input checked="" type="radio"/> FAIR · Attn
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn
BOOM	
No. of Section	2 SECTIONS
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR <input checked="" type="radio"/> DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	A/C · H/C · H only · C only <input checked="" type="radio"/> None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS X · H	
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn
COMMENT	
カゴ内でE/Gスタートできない UNABLE TO START THE ENGINE AT BUCKET	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。