

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/5/7	MAKE	KOMATSU	MODEL	D31S-17
SERIAL	32231		STAMP	D31S16-32231	
HR METER	1525	HR	SHOE	400G	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL	S/N	UNDERCARRIAGE	See Photos. 写真参照
Oil leakage	FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
Blow-By	FAIR · Attn	COMMENT	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
OPERATION PUMP		Ripper	MULTI · S/S Shanks PCS
Sound	FAIR · Attn	Ripper CYLD.	FAIR · Attn
Oil leakage	FAIR · Attn	COMMENT	
Power	FAIR · Attn	ウインチあり(油漏れあり) W/WINCH: OIL LEAKING	
COOLING SYSTEM		林業用グラップル: 左右シリンダー油漏れ、左右パッチあり	
Radiator	FAIR · Attn	GRAPPLE CYLINDERS: OIL LEAKING, GRAPPLE: PATCHED	
Oil Cooler	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	PS · DD	DIFF. STEERING	YES · NO
Transmission	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	破れあり TORN	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BLADE & CYLINDERS			
BLADE	FAIR · Attn	林業用グラップル GRAPPLE	
CYLD.(R)	FAIR · Attn		
CYLD.(L)	FAIR · Attn		
TILT CYLD	FAIR · Attn		
ANGLE CYLD	FAIR · Attn	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。