

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/6	MAKE	KOMATSU	MODEL	LW250-5
SERIAL No.	PLATE :	55001		STAMP :	L003-55001
HR METER	2662	HR	Odometer	1235	km
TIRE SIZE	385/95R25		YEAR	1997	YR

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Blow-By	<input type="radio"/> FAIR · <input type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Exhaust Color	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	黒煙あり BLACK FUMES
OPERATION PUMP		
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil leakage	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	油漏れあり OIL LEAKING
Power	<input type="radio"/> FAIR · <input type="radio"/> Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil Cooler	<input type="radio"/> FAIR · <input type="radio"/> Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · <input type="radio"/> NG	モニター映り悪い MONITOR: BLURRED
Swing	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Travel	<input type="radio"/> FAIR · <input type="radio"/> Attn	
TRANSMISSION		
Transmission	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	トルコン油漏れあり TORQUE CONVERTER: OIL LEAKING
No. OF GEARS	3	GEARS
4WD	<input checked="" type="radio"/> 4WD · <input type="radio"/> 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · <input type="radio"/> DIRTY	
Operator's Seat	<input type="radio"/> FAIR · <input type="radio"/> Attn	破れあり CUTS
Glasses	<input type="radio"/> FAIR · <input type="radio"/> Attn	
AirCon	<input checked="" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None	
COMMENT		
OSSエラー表示あり ERROR DISPLAY FOR ONLINE SYSTEM for SAFETY		

BOOM			
No. of Section	4	SECTIONS	
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · <input type="radio"/> Attn		
DERRICKING CYL.	<input type="radio"/> FAIR · <input type="radio"/> Attn		
EXTENSION CYL.	<input type="radio"/> FAIR · <input type="radio"/> Attn		
JIB	YES · <input checked="" type="radio"/> NO		
JIB TYPE	STD · <input type="radio"/> PWR		
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · <input type="radio"/> NO	主・補ワイヤーキンクあり WIRES: KINKED	
FREE FALL	<input type="radio"/> YES · <input checked="" type="radio"/> NO		
HOOK	26t, BALL		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR		<input checked="" type="radio"/> FAIR · <input type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR	
COMMENT			
リアステアロック不良 REAR STEERING LOCK: MALFUNCTION			
左右Fステアリングシリンダー油漏れあり FRONT STEERING CYLINDERS: OIL LEAKING			
OUTRIGGERS			
OUTRIGGERS	<input checked="" type="radio"/> X · <input type="radio"/> H		
OUTRIGGERS COND.	<input type="radio"/> FAIR · <input type="radio"/> Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
COMMENT			
基礎仕様 FOUNDATION WORK MACHINE			
ブーム背面スライド板欠 SOME BOOM TOP SLIDE PLATE: MISSING			
異音あり(プロペラシャフト周り?) AROUND PROPELLER SHAFT?: NOISES			
上部後ろカバー穴あり REAR COVER OF UPPER PART: MUCH CRACKED			
第3ドラム付 W/3rd DRUM			
E/Gオイルエレメント配管油漏れあり ENGINE OIL FILTER PIPES: OIL LEAKING			
ブレーキ油量ランプ点灯あり WARNING LAMP FOR BRAKE OIL LEVEL: ON			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。