INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/4/6	MAKE	TADANO	MODEL	AT-270-2
SERIAL No.	PLATE : 370873		STAMP : 370873		
HR METER	3932 HR	Odometer	34404 km	YEAR	2010 YR
CHASSIS	MODEL FC6JGW		No. 10734		
SHOE			TIRE SIZE	225/80R17.5	
MAX HIGHT	27.0 m		MAX WEIGHT	200 kg	

ENGINE : MODEL S/N		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	AT · (MT)	No. OF GEARS 6 GEARS
Transmission	(FAIR) · Attn	
4WD	4WD · (2WD)	
Travel	(FAIR) · Attn	
Swing	FAIR · Attn	
FOOT BRAKE	(FAIR) · Attn	
PARKING BRAKE	(FAIR) · Attn	
BOOM		
No. of Section	4 SECTIONS	
DERRICKING CYL.	(FAIR) · Attn	
EXTENSION CYL.	(FAIR) · Attn	

INTERIOR See Photos. 写真参照		
INTERIOR COND.	(CLEAN) · FAIR · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	(FAIR) · WORN · UNEVEN WEAR	
COMMENT		
OUTRIGGERS	X · (H)	
OUTRIGGERS COND.	(FAIR) · Attn	
COMMENT		
シャーシ刻印一部読めない CHASSIS STAMP: PARTLY UNREADABLE		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。