

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/5/13	MAKE	HITACHI	MODEL	ZX120-3
SERIAL	NO PLATE		STAMP	HCM1R100L00081528	
HR METER	8900	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · <u>Attn</u>	A LITTLE <u>MIDDLE</u> · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
MAIN PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · <u>Attn</u> *1	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	破れあり TORN
Glasses	<u>FAIR</u> · Attn	
AirCon	<u>A/C</u> · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> · Attn	
Boom Cylinder	<u>FAIR</u> · <u>Attn</u> *2	
Arm	<u>FAIR</u> · Attn	
Arm Cylinder	<u>FAIR</u> · <u>Attn</u> *3	
ATTACHMENT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · <u>Attn</u> *3	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	STD / SLOPE / NARROW <u>SKELETON</u> OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	<u>YES</u> · NO *4
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
COMMENT	
モニター一部表示不良 MONITOR: PARTLY NOT DISPLAYING	
*1 E/G低回転時ブームで車体上がらない	
*1 UNABLE TO PUSH UP THE BODY BY BOOM WITH LOW ENGINE SPEED	
*2 E/G低回転時動き遅い SLOW MOVING WITH LOW ENGINE SPEED	
*3 E/G低回転時動き遅い、途中で止まってまた動く	
*3 SLOW MOVING WITH LOW ENGINE SPEED,	
ALWAYS STOPPING TO MOVE HALFWAY ONCE & MOVING AGAIN	
*4 MLクレーン故障警告表示、クレーン警告灯点灯、警告音あり	
*4 "4" & "5" ERRORS DISPLAY, WARNING LAMPS & WARNING SOUNDS: ON	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。