

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/5/15	MAKE	KOMATSU	MODEL	PC60-7C
SERIAL	59670		STAMP	PC60-59670	
HR METER	11101	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	450G PADS	

**ENGINE : MODEL** 4D95LE-2 **S/N** 107403

Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	<input checked="" type="radio"/> YES	NO	

**MAIN PUMP**

Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	

**COOLING SYSTEM**

Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	

**OPERATING SYSTEM**

Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	

**INTERIOR** See Photos. 写真参照

INTERIOR COND.	CLEAN	·	FAIR	·	<input checked="" type="radio"/> DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	破れあり TORN		
Glasses	<input checked="" type="radio"/> FAIR	Attn			
AirCon	<input checked="" type="radio"/> A/C	·	H/C	·	H only · C only · None

**BOOM / ARM / BKT**

Boom	<input checked="" type="radio"/> FAIR	Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn	
Arm	<input checked="" type="radio"/> FAIR	Attn	溶接跡あり WELDED
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn	
ATTACHMENT	<input checked="" type="radio"/> FAIR	Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn	

**UNDERCARRIAGE :** See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

**COMMENT**

.....

.....

.....

.....

BKT STD / SLOPE / NARROW / SKELETON /  OTHER / FORK GRAB )

Lever LONG ·  WRIST

Multi MULTI · 2 ·  NO

ARM-CRANE YES ·  NO

BLADE  YES · NO

OFFSET YES ·  NO

OFFSET Cylinder FAIR · Attn

Piping YES ·  NO Breaker only · Multi

**COMMENT**

A/C冷えない A/C: MALFUNCTION

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。