INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/5/20	MAKE	CAT	MODEL	008CR
SERIAL	K0214490		STAMP	14490	
HR METER	1968 HR		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / (NONE)		SHOE	180R	

ENGINE : MODEL	D722	S/N	5G1046
Oil leakage	(FAIR) · Attn		
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	(FAIR) · Attn		
Oil	FAIR · (Attn)	油量多い HIGH ENGINE OIL LEVEL	
Exhaust Color	(FAIR) · Attn		
US EPA	YES · (NO)		
MAIN PUMP			
Sound	(FAIR) · Attn		
Oil leakage	(FAIR) · Attn		
Power	(FAIR) · Attn		
COOLING SYSTEM			
Radiator	(FAIR) · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	(FAIR) · Attn		
Travel	(FAIR) · Attn		
INTERIOR	See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY		
Operator's Seat	(FAIR) · Attn	破れあり HUGE CUTS	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · (None)		
BOOM / ARM / BKT			
Boom	(FAIR) · Attn		
Boom Cylinder	(FAIR) · Attn		
Arm	(FAIR) · Attn		
Arm Cylinder	(FAIR) · Attn		
ATTACHMENT	FAIR · (Attn)	ガタ大 MUCH LOOSE	
BKT Cylinder	(FAIR) · Attn		

UNDERCARRIAGE :	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
可変脚仕様 VARIABLE WIDTH UNDERCARRIAGE		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG · (WRIST)	
Multi	MULTI · 2 · (NO)	
ARM-CRANE	YES · (NO)	
BLADE	(YES) · NO	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · (NO)	Breaker only · Multi
COMMENT		
セーフティレバー不良 SAFETY LEVER: MALFUNCTION		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。