INSPECTION SHEET 検品書

CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/5/11	MAKE	YANMAR	MODEL	C50R-3C
SERIAL	47233			STAMP	YMRC503CNB0047233
HR METER	2300 + 916 HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / (CNP) / NONE	SHOE	450R	TIRE	

ENGINE : MODEL		S/N 149875
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	No. OF GEARS GEARS
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
Swing	FAIR · Attn	
Articulate	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	

MAIN FRAME		
MAIN FLAME	(FAIR) · Attn	
VESSEL		
VESSEL	(FAIR) · Attn	
REAR GATE TYPE	(NORMAL) · L-GATE (FLAT)	
REAR GATE	(FAIR) · Attn	
UNDERCARRIAGE:	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	

COMMENT

HRメーター交換あり HR METER: REPLACED

下周り油漏れ小 BOTTOM: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。