

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/6/3	MAKE	KATO	MODEL	HD1430Ⅲ-LC
SERIAL	KWJ857L1T70006029		STAMP	6029	
HR METER	5232	HR	YEAR	2007	YR
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b> 6D16 <b>S/N</b>	
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	YES · <u>NO</u>
<b>MAIN PUMP</b>	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
<b>COOLING SYSTEM</b>	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
<b>OPERATING SYSTEM</b>	
Swing	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
<b>INTERIOR See Photos. 写真参照</b>	
INTERIOR COND.	CLEAN · FAIR · <u>DIRTY</u>
Operator's Seat	<u>FAIR</u> · Attn
Glasses	<u>FAIR</u> · Attn 天窓割れあり SKYLIGHT: CRACKED
AirCon	<u>A/C</u> · H/C · H only · C only · None
<b>BOOM / ARM / BKT</b>	
Boom	<u>FAIR</u> · Attn *1
Boom Cylinder	<u>FAIR</u> · Attn
Arm	<u>FAIR</u> · Attn ヘコミ、ガタあり DENT, LOOSE
Arm Cylinder	<u>FAIR</u> · Attn
ATTACHMENT	<u>FAIR</u> · Attn
BKT Cylinder	<u>FAIR</u> · Attn

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <u>WRIST</u>
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u>
<b>COMMENT</b>	
3段ブーム 3-SECTION DEMOLITION FRONT	
ブーム周りホースひび割れあり SOME HOSE AROUND BOOM: CRACKED	
ポンプ周りバルブにじみあり SOME VALVE AROUND PUMP: OIL OOZING	
A/C冷えない A/C: MALFUNCTION	
安全レバー固着あり(下がらない)、不良(レバーロック効かない、機械動く)	
SAFETY LEVER: STUCK (UNABLE TO GO DOWN), MALFUNCTION	
リペイントあり REPAINTED	
左側中間ブーム操作ペダル固着気味	
LEFT PEDAL FOR INSERT BOOM: A LITTLE STUCK	
アタッチメントなし WITHOUT ATTACHMENT	
*1 パッチ、中間ブームガタあり PATCHED, INSERT BOOM: LOOSE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。