INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/5/8	MAKE	KOMATSU	MODEL	WA100-1
SERIAL	32561		STAMP	W005-32561	
HR METER	10582 HR	Odometer	27828 km	YEAR	YR
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE		TIRE SIZE	16.9-24	

ENGINE : MODEL 6D95L S/N 77386		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS)・ DD	
Transmission	FAIR ・(Attn)	にじみあり OIL OOZING
Travel	(FAIR)・ Attn	
FOOT BRAKE	(FAIR)・ Attn	
PARKING BRAKE	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	破れあり CUTS
Glasses	(FAIR)・ Attn	
AirCon	A/C ・ H/C ・(H only) ・ C only ・ None	
FRONT & CYLINDERS		
Arm	(FAIR)・ Attn	
Bell crank	(FAIR)・ Attn	
Bucket	(FAIR)・ Attn	
Articulate	(FAIR)・ Attn	ガタあり LOOSE

UNDERCARRIAGE : See Photos. 写真参照			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		
TIRE WEAR	(FAIR) ・WORN ・ UNEVEN WEAR		
COMMENT			
STEERING TYPE	(WHEEL STEERING) / COMMAND STEERING / LEVER STEERING		
RIDE CONTROL	YES ・(NO)		
ATTACHMENTS			
STD BKT	(YES)・ OTHER		
BLADE	YES ・(NO)	Piping for Tilt	YES ・(NO)
COMMENT			
リペイントあり REPAINTED			
燃料メーター不良 FUEL GAUGE: MALFUNCTION			
*1 エキゾーストマニホールド周りにじみあり			
*1 AROUND EXHAUST MANIFOLD: OIL OOZING			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。