

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/5/13	MAKE	CAT	MODEL	D5B
SERIAL	49X02102			STAMP	49X02102
HR METER	6691	HR	SHOE	860LGP	YEAR YR
BLADE	STRAIGHT <input checked="" type="radio"/> ST/TILT <input type="radio"/> PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS <input checked="" type="radio"/> CNP <input type="radio"/> NONE	

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · <input checked="" type="radio"/> DD	DIFF. STEERING YES · <input checked="" type="radio"/> NO
Transmission	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · <input type="radio"/> DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None	
BLADE & CYLINDERS		
BLADE	<input checked="" type="radio"/> FAIR · Attn	溶接あり WELDED
CYLD.(R)	<input checked="" type="radio"/> FAIR · Attn	
CYLD.(L)	<input checked="" type="radio"/> FAIR · Attn	
TILT CYLD	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	サビあり RUSTY
ANGLE CYLD	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<input checked="" type="radio"/> FAIR · Attn		
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。