INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/4/30	MAKE	HITACHI	MODEL	ZX75US-A
SERIAL	HCM1CG00H00045909		STAMP	HCM1CG00H00045909	
HR METER	7156 HR		YEAR	YR	
CAB/CNP	ROPS CAB (/ CAB /) ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL 4JG1 S/N 339569		
Oil leakage	FAIR ・(Attn)	下周り油漏れ小 BOTTOM: OIL LEAKING
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	(YES)・ NO	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	ガタあり SWING: LOOSE
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・ (FAIR)・ DIRTY	
Operator's Seat	(FAIR)・ Attn	
Glasses	(FAIR)・ Attn	
AirCon	(A/C)・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	ガタあり LOOSE
Boom Cylinder	FAIR ・(Attn)	傷、にじみあり SCRATCHED, OIL OOZING
Arm	(FAIR)・ Attn	ガタあり LOOSE
Arm Cylinder	(FAIR)・ Attn	
ATTACHMENT	(FAIR)・ Attn	
BKT Cylinder	FAIR ・(Attn)	傷、油漏れ小 SCRATCHED, OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG ・ (WRIST)	
Multi	MULTI ・ 2 (・ NO)	
ARM-CRANE	YES ・(NO)	
BLADE	YES ・(NO)	
OFFSET	YES ・(NO)	
OFFSET Cylinder	FAIR ・ Attn	
Piping	(YES)・ NO	Breaker only (・ Multi)
COMMENT		
ローアイドルでリリーフ掛けるとエンストする		
ENGINE STALLING WITH ENGINE LOAD INCREASING IN LOW IDLING		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。