

**INSPECTION SHEET 検品書**  
**OTHER その他**

INSPECTION DATE	2026/5/7	CATEGORY	SHOE LINK ASSY for ZX120		
MAKE	UNKNOWN		MODEL	UNKNOWN	
SERIAL	-		STAMP	-	
HR METER	-	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	TIRE

ENGINE	MODEL	S/N			
Oil leakage	FAIR · Attn		Oil	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	FAIR · Attn	
Sound	FAIR · Attn		EPA	YES · NO	

CONDITION	FAIR · Attn
未確認 OPERATION: NOT CHECKED	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
<b>COMMENT</b>			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	-		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。