

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/5/28	MAKE	KOBELCO	MODEL	7050
SERIAL No.	PLATE : FP02-01176	STAMP	FP02-01176		
HR METER	UNKNOWN	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL S/N	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn にじみあり OIL Oozing
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
BOOM	
MAIN BOOM	TOP, BOTTOM, 9m × 1, 6m × 3, 3m × 2
BOOM TOTAL	42m
TOP SHEAVE	<input checked="" type="radio"/> YES · NO
JIB	
TOWER	

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
左右キヤタたるみあり TRACK LINKS: WORN	
WEIGHT	3
HOOK	50t, 32t, 19t, BALL
FREE FALL	<input checked="" type="radio"/> YES · NO
LIFTER	YES · <input checked="" type="radio"/> NO
COMMENT	
CAB穴あり CAB: HUGE HOLE	
トップブームラチス曲がりあり SOME LATTICE PIPES OF TOP BOOM: BENT	
ガントリーシリンダー1本油漏れあり SOME GANTRY CYLINDER: OIL LEAKING	
@NARITA YARD	
BOOM: TOP, BOTTOM, 6m × 1	
@SAKURA YARD	
BOOM: 9m × 1, 6m × 2, 3m × 2	
HOOK: 32t, 19t	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。