INSPECTION SHEET 検品書
DUMP TRUCK ダンプ

INSPECTION DATE	2026/5/14	CATEGORY	(ON-ROAD DUMP) ・ OFF-ROAD DUMP
MAKE	HINO	MODEL	FC9JCA
SERIAL	10252	STAMP	FC9JCA-10252
HR METER	UNKNOWN HR	ODOMETER	175145 km
TIRE SIZE	225/80R17.5	YEAR	YR

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) ・ Attn	
Blow-By	(FAIR) ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	(FAIR) ・ Attn	
US EPA	YES ・(NO)	

OPERATION PUMP		
Sound	(FAIR) ・ Attn	
Oil leakage	(FAIR) ・ Attn	
Power	(FAIR) ・ Attn	

COOLING SYSTEM		
Radiator	(FAIR) ・ Attn	
Oil Cooler	(FAIR) ・ Attn	

TRANSMISSION & TRAVEL				
T/M TYPE	AT ・(MT)		No. OF GEARS	6 GEARS
Transmission	(FAIR) ・ Attn			
4WD	4WD ・(2WD)			
Travel	(FAIR) ・ Attn			
Articulate	FAIR ・ Attn			
FOOT BRAKE	(FAIR) ・ Attn			
PARKING BRAKE	(FAIR) ・ Attn			

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	FAIR ・(Attn)	破れあり CUTS
Glasses	(FAIR) ・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	

MAIN FRAME		
MAIN FLAME	(FAIR) ・ Attn	

VESSEL		
MAKE	SHIN MAYWA DR4-17SY	
VESSEL	(FAIR) ・ Attn	
REAR GATE TYPE	(NORMAL) ・ L-GATE (FLAT)	
REAR GATE	(FAIR) ・ Attn	

UNDERCARRIAGE: See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	(FAIR) ・ WORN ・ UNEVEN WEAR	

COMMENT

最大積載量 MAXIMUM LOADING: 3750kg

スペアタイヤあり W/SPARE TIRE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。