# INSPECTION SHEET 検品書
## DUMP TRUCK ダンプ

| | | | |
|---|---|---|---|
| INSPECTION DATE | 2026/5/14 | CATEGORY | (ON-ROAD DUMP) ・ OFF-ROAD DUMP |
| MAKE | ISUZU | MODEL | TKG-FRR90S1 |
| SERIAL | FRR90-7061518 | STAMP | FRR90-7061518 |
| HR METER | UNKNOWN HR | ODOMETER | 127728 km |
| TIRE SIZE | 225/80R17.5 | YEAR | YR |

| ENGINE : MODEL | | S/N |
|---|---|---|
| Oil leakage | (FAIR) ・ Attn | |
| Blow-By | (FAIR) ・ Attn | A LITTLE ・ MIDDLE ・ SEVERE |
| Sound | (FAIR) ・ Attn | |
| Oil | (FAIR) ・ Attn | |
| Exhaust Color | (FAIR) ・ Attn | |
| US EPA | YES ・(NO) | |

| OPERATION PUMP | | |
|---|---|---|
| Sound | (FAIR) ・ Attn | |
| Oil leakage | (FAIR) ・ Attn | |
| Power | (FAIR) ・ Attn | |

| COOLING SYSTEM | | |
|---|---|---|
| Radiator | (FAIR) ・ Attn | |
| Oil Cooler | (FAIR) ・ Attn | |

| TRANSMISSION & TRAVEL | | | | |
|---|---|---|---|---|
| T/M TYPE | AT ・(MT) | | No. OF GEARS | 6 GEARS |
| Transmission | (FAIR) ・ Attn | | | |
| 4WD | 4WD ・(2WD) | | | |
| Travel | (FAIR) ・ Attn | | | |
| Articulate | (FAIR) ・ Attn | | | |
| FOOT BRAKE | (FAIR) ・ Attn | | | |
| PARKING BRAKE | (FAIR) ・ Attn | | | |

| INTERIOR See Photos. 写真参照 | | |
|---|---|---|
| INTERIOR COND. | CLEAN ・ (FAIR) ・ DIRTY | |
| Operator's Seat | (FAIR) ・ Attn | |
| Glasses | (FAIR) ・ Attn | |
| AirCon | (A/C) ・ H/C ・ H only ・ C only ・ None | |

| MAIN FRAME | | |
|---|---|---|
| MAIN FLAME | (FAIR) ・ Attn | |

| VESSEL | | |
|---|---|---|
| MAKE | UNKNOWN | |
| VESSEL | (FAIR) ・ Attn | |
| REAR GATE TYPE | (NORMAL) ・ L-GATE (FLAT) | |
| REAR GATE | (FAIR) ・ Attn | |

| UNDERCARRIAGE: See Photos. 写真参照 | |
|---|---|
| **RUST** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
| TIRE WEAR | (FAIR) ・ WORN ・ UNEVEN WEAR |

**COMMENT**

最大積載量 MAXIMUM LOADING: 3800kg

スペアタイヤあり W/SPARE TIRE

| | |
|---|---|
| **RUST of BODY** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。