

INSPECTION SHEET 検品書  
CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/5/15	MAKE	YANMAR	MODEL	C12R
SERIAL	21066C		STAMP	21066C	
HR METER	2566	HR	Odometer	-	km
				YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	230R	TIRE

<b>ENGINE : MODEL</b>		<b>S/N</b>	42568
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
<b>OPERATION PUMP</b>			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
<b>COOLING SYSTEM</b>			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	PS	DD	
	No. OF GEARS		GEARS
Transmission	FAIR	Attn	
Travel	FAIR	Attn	
Swing	FAIR	Attn	
Articulate	FAIR	Attn	
FOOT BRAKE	FAIR	Attn	
PARKING BRAKE	FAIR	Attn	
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn 破れあり CUTS	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

<b>MAIN FRAME</b>	
MAIN FLAME	FAIR · Attn
<b>VESSEL</b>	
VESSEL	FAIR · Attn コンクリ付着あり CONCRETE STAINS
REAR GATE TYPE	NORMAL · L-GATE (FLAT)
REAR GATE	FAIR · Attn
<b>UNDERCARRIAGE: See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。