

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/5/14	MAKE	KOBELCO	MODEL	SK75SRD-3
SERIAL	NO PLATE		STAMP	YT07-28132	
HR METER	5731	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

**ENGINE : MODEL** 4LE2 **S/N** 624618

Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	EC/EU

**MAIN PUMP**

Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

**COOLING SYSTEM**

Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

**OPERATING SYSTEM**

Swing	FAIR	Attn
Travel	FAIR	Attn

**INTERIOR** See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり CUTS
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

**BOOM / ARM / BKT**

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	ガタあり LOOSE
BKT Cylinder	FAIR	Attn	

**UNDERCARRIAGE :** See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT (STD) / SLOPE / NARROW / SKELETON / OTHER ( )	
Lever	LONG · (WRIST)
Multi	(MULTI) · 2 · NO
ARM-CRANE	(YES) · NO *2
BLADE	(YES) · NO
OFFSET	YES · (NO)
OFFSET Cylinder	FAIR · Attn
Piping	(YES) · NO Breaker only · (Multi)

**COMMENT**

A/C効かない A/C: MALFUNCTION  
 \*1 ヘッドカバー、フロントカバー周り油漏れ小  
 \*1 AROUND HEAD COVER & FRONT COVER: OIL LEAKING  
 \*2 クレーン荷重センサー故障、アラーム作動あり  
 \*2 CRANE LOAD SENSOR: MALFUNCTION, WARNING SOUNDS: ON

**RUST of BODY** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。