INSPECTION SHEET 検品書

ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/6/12	MAKE	KATO	MODEL	KR-20H-L
SERIAL No.	PLATE : 1211013		STAMP : KRC001-1013		
HR METER	21919 HR		Odometer	93662 km	
TIRE SIZE	325/95R24		YEAR	2007 YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR・(Attn)	ヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	(FAIR)・Attn	A LITTLE・MIDDLE・SEVERE
Sound	(FAIR)・Attn	
Oil	(FAIR)・Attn	
Exhaust Color	(FAIR)・Attn	
OPERATION PUMP		
Sound	(FAIR)・Attn	
Oil leakage	(FAIR)・Attn	
Power	(FAIR)・Attn	
COOLING SYSTEM		
Radiator	(FAIR)・Attn	
Oil Cooler	(FAIR)・Attn	
OPERATING SYSTEM		
Computer	(OK)・NG	
Swing	FAIR・(Attn)	旋回ガタあり SWING: LOOSE
Travel	(FAIR)・Attn	
TRANSMISSION		
Transmission	(FAIR)・Attn	
No. OF GEARS	3 GEARS	
4WD	(4WD)・6WD	

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN・(FAIR)・DIRTY
Operator's Seat	(FAIR)・Attn
Glasses	(FAIR)・Attn
AirCon	(A/C)・H/C・H only・C only・None

COMMENT

A/C効かない A/C: MALFUNCTION

BOOM		
No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	(FAIR)・Attn	
DERRICKING CYL.	(FAIR)・Attn	
EXTENSION CYL.	(FAIR)・Attn	
JIB	(YES)・NO	
JIB TYPE	STD・(PWR)	
MAIN & SUB WIRE	(YES)・NO	
FREE FALL	YES・(NO)	
HOOK	20t, BALL	

UNDERCARRIAGE : See Photos. 写真参照

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR・(WORN)・UNEVEN WEAR

COMMENT

OUTRIGGERS

OUTRIGGERS	X・(H)			
OUTRIGGERS COND.	(FAIR)・Attn			
Oil leakage (JACK CYL.)	FRONT	L・R	REAR	L・R
Oil leakage (SLIDE CYL.)	FRONT	L・R	REAR	L・R

COMMENT

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。