

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/5/15	MAKE	KOMATSU	MODEL	PC200-10
SERIAL	454638		STAMP	KMTPC243AGC454638	
HR METER	9856	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 6D107E-2 S/N 26648346	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO

MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn にじみあり OIL OOZING
Power	FAIR · Attn

COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn

OPERATING SYSTEM	
Swing	FAIR · Attn ガタあり SWING: LOOSE
Travel	FAIR · Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れあり TORN
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT	
Boom	FAIR · Attn クラックあり CRACKED
Boom Cylinder	FAIR · Attn
Arm	FAIR · Attn ガタあり LOOSE
Arm Cylinder	FAIR · Attn 油漏れあり OIL LEAKING
ATTACHMENT	FAIR · Attn ガタあり LOOSE
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

COMMENT	

BKT	STD (SLOPE) NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi *1

COMMENT	
リペイントあり REPAINTED	
*1 左右配管欠、ペダルロック固着あり	
*1 PIPES: PARTLY MISSING, PEDAL LOCK: STUCK	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。