

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/5/1	CATEGORY	農業用コンバイン COMBINE HARVESTER			
MAKE	YANMAR		MODEL	GC800		
SERIAL	010197		STAMP	NOT FOUND		
HR METER	2037	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB	<input checked="" type="radio"/> CAB	ROPS CNP / CNP / NONE	SHOE	540R	TIRE

ENGINE	MODEL	4TNE98	S/N	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	Oil	<input checked="" type="radio"/> FAIR
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE	MIDDLE
			SEVERE	Exhaust Color
Sound	<input checked="" type="radio"/> FAIR	Attn	EPA	YES
				<input checked="" type="radio"/> NO

CONDITION	<input checked="" type="radio"/> FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR	WORN	UNEVEN WEAR
--	---	-----------	------	------	-------------

COMMENT

A/C故障あり A/C: MALFUNCTION

ラジオ故障あり RADIO: MALFUNCTION

イス破れあり SEAT: CUT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。