

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2026/6/8	MAKE	HITACHI	MODEL	CX550-C
SERIAL No.	PLATE : 24EP002142	STAMP	24EP002142		
HR METER	11605	HR	SHOE	760FLAT	YEAR YR

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATION PUMP</b>		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK · NG	未確認 NOT CHECKED
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
<b>BOOM</b>		
MAIN BOOM	TOP, BOTTOM, 9m × 2, 6m × 1, 3m × 1	
BOOM TOTAL	37m	
TOP SHEAVE	<input checked="" type="radio"/> YES · NO	
JIB		
TOWER		

<b>INTERIOR</b>		<b>See Photos. 写真参照</b>
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
<b>UNDERCARRIAGE : See Photos. 写真参照</b>		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	
<b>COMMENT</b>		
キャタタるみあり TRACK LINKS: WORN		
WEIGHT	3	
HOOK	55t, 30t, BALL	
FREE FALL	<input checked="" type="radio"/> YES · NO	
LIFTER	<input checked="" type="radio"/> YES · NO	
<b>COMMENT</b>		
@NARITA YARD		
BOOM: TOP, BOTTOM, 9m × 1		
@PARKING SITE OF NARITA YARD		
BOOM: 9m × 1, 6m × 1, 3m × 1		
30t HOOK		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。