

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/6/3	MAKE	HITACHI	MODEL	ZX200-6
SERIAL	HCMD C4A0L00507345		STAMP	HCMD C4A0L00507345	
HR METER	6154	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	800G	

ENGINE : MODEL	4HK1	S/N	799678
Oil leakage	<input checked="checked" type="radio"/> FAIR · Attn		
Blow-By	<input checked="checked" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="checked" type="radio"/> FAIR · Attn		
Oil	<input checked="checked" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="checked" type="radio"/> FAIR · Attn		
US EPA	<input checked="checked" type="radio"/> YES · NO		
MAIN PUMP			
Sound	<input checked="checked" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="checked" type="radio"/> FAIR · Attn		
Power	<input checked="checked" type="radio"/> FAIR · Attn		
COOLING SYSTEM			
Radiator	<input checked="checked" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="checked" type="radio"/> FAIR · Attn		
OPERATING SYSTEM			
Swing	<input checked="checked" type="radio"/> FAIR · Attn		
Travel	<input checked="checked" type="radio"/> FAIR · Attn		
INTERIOR	See Photos. 写真参照		
INTERIOR COND.	CLEAN · <input checked="checked" type="radio"/> FAIR · DIRTY		
Operator's Seat	<input checked="checked" type="radio"/> FAIR · Attn	穴あり HOLES	
Glasses	<input checked="checked" type="radio"/> FAIR · Attn		
AirCon	<input checked="checked" type="radio"/> A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	<input checked="checked" type="radio"/> FAIR · Attn		
Boom Cylinder	<input checked="checked" type="radio"/> FAIR · Attn		
Arm	<input checked="checked" type="radio"/> FAIR · Attn	ガタあり LOOSE	
Arm Cylinder	<input checked="checked" type="radio"/> FAIR · Attn		
ATTACHMENT	<input checked="checked" type="radio"/> FAIR · Attn		
BKT Cylinder	<input checked="checked" type="radio"/> FAIR · Attn		

UNDERCARRIAGE :	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
BKT	<input checked="checked" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG · <input checked="checked" type="radio"/> WRIST	
Multi	<input checked="checked" type="radio"/> MULTI · 2 · NO	
ARM-CRANE	<input checked="checked" type="radio"/> YES · NO	
BLADE	YES · <input checked="checked" type="radio"/> NO	
OFFSET	YES · <input checked="checked" type="radio"/> NO	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · <input checked="checked" type="radio"/> NO	Breaker only · Multi
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。