

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/5/20	MAKE	MITSUBISHI	MODEL	BS3F
SERIAL	1S500645		STAMP	1S500645	
HR METER	1109	HR	SHOE	300G	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N	3421
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	YES · <input checked="" type="radio"/> NO		
OPERATION PUMP			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	<input checked="" type="radio"/> PS · DD	DIFF. STEERING	YES · <input checked="" type="radio"/> NO
Transmission	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY		
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn 左アームレスト破れあり LEFT ARMREST: CUT	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None		
BLADE & CYLINDERS			
BLADE	<input checked="" type="radio"/> FAIR	Attn	
CYLD.(R)	<input checked="" type="radio"/> FAIR	Attn	
CYLD.(L)	<input checked="" type="radio"/> FAIR	Attn	
TILT CYLD	<input checked="" type="radio"/> FAIR	Attn	
ANGLE CYLD	<input checked="" type="radio"/> FAIR	Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Ripper MULTI · S/S Shanks PCS Ripper CYLD. FAIR · Attn </div>			
COMMENT			
ドーザーショベル DOZER-SHOVEL リペイントあり REPAINTED CNPヘッドガード欠 HEAD GUARD: MISSING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。