

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/5/14	MAKE	CAT	MODEL	320D-E
SERIAL	CAT0320DTBWZ07141		STAMP	CAT0320DTBWZ07141	
HR METER	9676 / 9677	HR	YEAR	YR	
CAB/CNP	ROPS CAB (CAB) ROPS CNP / CNP / NONE	SHOE	790G		

<b>ENGINE : MODEL</b>		S/N	GDC68386
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
<b>MAIN PUMP</b>			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
<b>COOLING SYSTEM</b>			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
<b>OPERATING SYSTEM</b>			
Swing	FAIR · Attn		
Travel	FAIR · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
<b>BOOM / ARM / BKT</b>			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn	左側油漏れあり LEFT CYLINDER: OIL LEAKING	
Arm	FAIR · Attn		
Arm Cylinder	FAIR · Attn		
ATTACHMENT	FAIR · Attn	ガタあり LOOSE	
BKT Cylinder	FAIR · Attn		

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。