INSPECTION SHEET 検品書
MOTOR GRADER グレーダー

INSPECTION DATE	2026/5/14	MAKE	MITSUBISHI	MODEL	MG300
SERIAL	3G000798			STAMP	3G000798
HR METER	E5335 HR	Odometer	43079 km	YEAR	YR
SCARIFIER	(YES) ・ NO	3		BLADE	3400 mm
CAB/CNP	(CAB) / CNP / NONE			TIRE SIZE	12.00-24

ENGINE : MODEL	S/N	
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS)・ DD	
Transmission	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
FOOT BRAKE	(FAIR)・ Attn	
PARKING BRAKE	FAIR ・(Attn)	効かない MALFUNCTION
INTERIOR	**See Photos. 写真参照**	
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	
Glasses	(FAIR)・ Attn	
AirCon	A/C ・ H/C ・ (H only) ・ C only ・ None	
HYD. CYLINDER		
For Blade	(FAIR)・ Attn	
For Scarifier	(FAIR)・ Attn	
Articulate	FAIR ・(Attn)	*2

UNDERCARRIAGE : See Photos. 写真参照	
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR (・ WORN ・) UNEVEN WEAR

COMMENT

ステアリングシリンダーにじみあり STEERING CYLINDER: OIL OOZING

サークルモーター下油漏れ小

LOWER PART OF CIRCLE MOTOR: OIL LEAKING

ミッション下ドレーン周りにじみあり

AROUND DRAIN UNDER TRANSMISSION: OIL OOZING

オイルゲージ破損あり、緩い OIL GAUGE: BROKEN, LOOSE

サークルスイング用シリンダーにじみあり

CIRCLE SWING CYLINDER: OIL OOZING

HRメーターストップ HR METER: STOPPED

燃料メーター不良 FUEL GAUGE: MALFUNCTION

ニュートラルレバー中立甘い SHIFT LEVER: HARD TO SHIFT IN NEUTRAL

*1 ブロック周りにじみあり AROUND ENGINE BLOCK: OIL OOZING

*2 左側にじみ、右側油漏れあり

*2 LEFT CYLINDER: OIL OOZING, RIGHT CYLINDER: OIL LEAKING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。