

INSPECTION SHEET 検品書  
CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/5/22	MAKE	MOROOKA	MODEL	MST-2300VD
SERIAL	234272		STAMP	234272	
HR METER	3130	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	740R	TIRE
					2017 YR

<b>ENGINE : MODEL</b>		<b>S/N</b>	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
<b>OPERATION PUMP</b>			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
<b>COOLING SYSTEM</b>			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	PS · DD	No. OF GEARS	2 GEARS
Transmission	FAIR · Attn		
Travel	FAIR · Attn		
Swing	FAIR · Attn		
Articulate	FAIR · Attn		
FOOT BRAKE	FAIR · Attn		
PARKING BRAKE	FAIR · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	穴あり HOLE	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		

<b>MAIN FRAME</b>	
MAIN FLAME	FAIR · Attn
<b>VESSEL</b>	
VESSEL	FAIR · Attn
REAR GATE TYPE	NORMAL · L-GATE (FLAT)
REAR GATE	FAIR · Attn
<b>UNDERCARRIAGE: See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。