

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/5/19	MAKE	SUMITOMO	MODEL	SH120LPC
SERIAL	120P1-1122		STAMP	120P1-1122	
HR METER	4175	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE MIDDLE SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	

MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	配管にじみあり SOME PIPE: OIL OOZING
Power	FAIR · Attn	

COOLING SYSTEM		
Radiator	FAIR · Attn	オイル混入あり OIL: MIXED
Oil Cooler	FAIR · Attn	

OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	

BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	*1
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT	
右側ピンブッシュ割れあり SOME RIGHT PIN BUSHES: BROKEN	

BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi *2

COMMENT	
底板欠 SOME UNDER COVERS: MISSING	
全体的にホースヒビ、破れあり MANY HOSE: A LITTLE DAMAGED	
モニター表示不良 MONITOR: MALFUNCTION	
スライドCAB SLIDE CAB	
アクセル: ダイヤルでコントロール不可	
ACCELERATOR: UNABLE TO CONTROL BY ACCELERATOR KNOB	
*1 左側にじみ、左右ホース油漏れ小	
*1 LEFT CYLINDER: OIL OOZING, HOSES: OIL LEAKING	
*2 テレスコーム用配管あり W/PIPING FOR TELESCOPIC ARM	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。