INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/5/26	MAKE	KOMATSU	MODEL	PC120
SERIAL	NO PLATE			STAMP	PC120-54280
HR METER	8086 HR			YEAR	YR
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL 4D102E-1 S/N 26202110		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	FAIR ・(Attn)	油漏れあり OIL LEAKING
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	FAIR ・(Attn)	*2
Oil Cooler	(FAIR)・ Attn	油汚れあり OIL STAINS
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	ガタあり SWING: LOOSE
Travel	(FAIR)・ Attn	HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・ FAIR・ (DIRTY)	
Operator's Seat	FAIR ・(Attn)	フレーム露出あり TORN
Glasses	(FAIR)・ Attn	
AirCon	(A/C)・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	ガタあり LOOSE
Boom Cylinder	(FAIR)・ Attn	
Arm	(FAIR)・ Attn	ガタあり LOOSE
Arm Cylinder	(FAIR)・ Attn	
ATTACHMENT	(FAIR)・ Attn	ガタあり LOOSE
BKT Cylinder	FAIR ・(Attn)	にじみあり OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	
COMMENT		
左走行モーターにじみあり LEFT TRAVEL MOTOR: OIL OOZING		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG ・ (WRIST)	
Multi	MULTI ・ 2 (・ NO)	
ARM-CRANE	YES ・(NO)	
BLADE	YES ・(NO)	
OFFSET	YES ・(NO)	
OFFSET Cylinder	FAIR ・ Attn	
Piping	YES ・(NO)	Breaker only ・ Multi
COMMENT		
A/Cコンプレッサー欠 COMPRESSOR FOR A/C: MISSING		
A/C風出ない A/C: NOT BLOWING AIR		
*1 ヘッド周り、E/G下周り油漏れあり		
*1 AROUND CYLINDER HEAD & BOTTOM OF ENGINE: OIL LEAKING		
*2 オイル混入、リザーブタンクホース切れあり		
*2 OIL: MIXED, RESERVE TANK HOSE: CUT		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。