

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/6/1	MAKE	KOBELCO	MODEL	SK75SR-3
SERIAL	YT07-27774		STAMP	YT07-27774	
HR METER	3885	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL	4LE2	S/N	620175
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	YES · <input checked="" type="radio"/> NO		

MAIN PUMP			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	

COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	

OPERATING SYSTEM			
Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	

INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY		
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn 破れあり TORN	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None		

BOOM / ARM / BKT			
Boom	<input checked="" type="radio"/> FAIR	Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn	
Arm	<input checked="" type="radio"/> FAIR	Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn	
ATTACHMENT	<input checked="" type="radio"/> FAIR	Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	<input checked="" type="radio"/> YES · NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi *1

COMMENT	
燃料フィルタ交換、作動油フィルタ交換、E/Gオイル交換表示あり	
WARNINGS DISPLAY FOR FUEL FILTER REPLACEMENT,	
HYDRAULIC OIL FILTER REPLACEMENT,	
& ENGINE OIL REPLACEMENT	
*1 切替えバルブ周りにじみあり AROUND SWITCH VALVE: OIL Oozing	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。