INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/5/18	CATEGORY	SNOW BLADE				
MAKE	UNKNOWN			MODEL	UNKNOWN		
SERIAL	–			STAMP	–		
HR METER	– HR	Odometer	km		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE		TIRE		

ENGINE	MODEL		S/N		
Oil leakage	FAIR ・ Attn		Oil	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color	FAIR ・ Attn	
Sound	FAIR ・ Attn		EPA	YES ・ NO	

CONDITION	FAIR ・ Attn	

未確認 OPERATION: NOT CHECKED

UNDERCARRIAGE : See Photos. 写真参照			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	–	TIRE WEAR	FAIR ・WORN・ UNEVEN WEAR

COMMENT

50φ ×90mm

左右底面ソリ欠 SLEDS OF BLADE: MISSING

右シリンダーロッドサビ大 RIGHT CYLINDER ROD: MUCH RUSTY

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。