INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/6/11	MAKE	KOMATSU	MODEL	WA200-3
SERIAL	60692			STAMP	W038-60692
HR METER	16945 HR	Odometer	– km	YEAR	YR
CAB/CNP	ROPS CAB (/ CAB /) ROPS CNP / CNP / NONE			TIRE SIZE	17.5-25

ENGINE : MODEL	S/N	
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	FAIR ・(Attn)	水:サビあり SOME RUST IN COOLANT
Oil Cooler	(FAIR)・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS)・ DD	
Transmission	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
FOOT BRAKE	(FAIR)・ Attn	
PARKING BRAKE	(FAIR)・ Attn	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	
Glasses	(FAIR)・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	
FRONT & CYLINDERS		
Arm	(FAIR)・ Attn	ストレートアーム STRAIGHT ARM
Bell crank	(FAIR)・ Attn	
Bucket	(FAIR)・ Attn	
Articulate	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		
TIRE WEAR	FAIR (・ WORN ・) UNEVEN WEAR		
COMMENT			
STEERING TYPE	(WHEEL STEERING / COMMAND STEERING / LEVER STEERING)		
RIDE CONTROL	YES ・ (NO)		
ATTACHMENTS			
STD BKT	(YES)・ OTHER		
BLADE	YES ・ (NO)	Piping for Tilt	YES ・ (NO)
COMMENT			
CAB下油漏れあり BOTTOM OF CAB: OIL LEAKING			
ラジエータフードラッチ破損あり RADIATOR HOOD LATCH: BROKEN			
正面メーター表示薄い FRONT MONITOR: BLURRED			
右側メーター不良(燃料等) RIGHT SIDE METERS: MALFUNCTION			
A/Cベルト欠、コンプレッサー固着あり			
A/C: NO BELT, COMPRESSOR: STUCK			
*1 ヘッド周りにじみあり AROUND CYLINDER HEAD: OIL OOZING			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。