

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/5/22	MAKE	KOMATSU	MODEL	PC200-7
SERIAL	251706		STAMP	KMTPC049A02251706	
HR METER	UNKNOWN	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b> 6D102E-2 <b>S/N</b> 26345307	
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	<u>YES</u> · NO
<b>MAIN PUMP</b>	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
<b>COOLING SYSTEM</b>	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
<b>OPERATING SYSTEM</b>	
Swing	<u>FAIR</u> · <u>Attn</u> 若干ゴリゴリ感あり A LITTLE RATTLING
Travel	<u>FAIR</u> · Attn
<b>INTERIOR See Photos. 写真参照</b>	
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY
Operator's Seat	<u>FAIR</u> · Attn 破れあり TORN
Glasses	<u>FAIR</u> · Attn
AirCon	<u>A/C</u> · H/C · H only · C only · None
<b>BOOM / ARM / BKT</b>	
Boom	<u>FAIR</u> · Attn
Boom Cylinder	<u>FAIR</u> · Attn
Arm	<u>FAIR</u> · Attn
Arm Cylinder	<u>FAIR</u> · Attn
ATTACHMENT	<u>FAIR</u> · <u>Attn</u> ガタあり LOOSE
BKT Cylinder	<u>FAIR</u> · Attn

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
右側トラックローラー不良あり SOME RIGHT TRACK ROLLER: MALFUNCTION	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	<u>YES</u> · NO *1
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
<b>COMMENT</b>	
*1 モードは入るがクレーンモードエラーの警告音が鳴るが ディスプレイ不鮮明のため何の警告音かは不明	
*1 WARNING SOUNDS: ON BUT UNKNOWN FOR WHAT ERROR (NONITOR: BLURRED), CRANE MODE: ABLE TO TURN ON	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。