INSPECTION SHEET 検品書

CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/5/14	MAKE	MOROOKA	MODEL	MST-800VD
SERIAL	020109			STAMP	020109
HR METER	246 HR	Odometer	km	YEAR	2022 YR
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE			SHOE	610R
TIRE					

ENGINE : MODEL	C4.4	S/N	44810525
Oil leakage	(FAIR) · Attn		
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	(FAIR) · Attn		
Oil	(FAIR) · Attn		
Exhaust Color	(FAIR) · Attn		
US EPA	YES · (NO)		
OPERATION PUMP			
Sound	(FAIR) · Attn		
Oil leakage	(FAIR) · Attn		
Power	(FAIR) · Attn		
COOLING SYSTEM			
Radiator	(FAIR) · Attn		
Oil Cooler	(FAIR) · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	(PS) · DD	No. OF GEARS	2 GEARS
Transmission	(FAIR) · Attn		
Travel	(FAIR) · Attn		
Swing	FAIR · Attn		
Articulate	FAIR · Attn		
FOOT BRAKE	FAIR · Attn		
PARKING BRAKE	(FAIR) · Attn		
INTERIOR	See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY		
Operator's Seat	(FAIR) · Attn		
Glasses	(FAIR) · Attn		
AirCon	(A/C) · H/C · H only · C only · None		

MAIN FRAME		
MAIN FLAME	(FAIR) · Attn	
VESSEL		
VESSEL	(FAIR) · Attn	
REAR GATE TYPE	(NORMAL) · L-GATE (FLAT)	
REAR GATE	(FAIR) · Attn	
UNDERCARRIAGE:	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。