

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/5/26	CATEGORY	SHOE LINK ASSY for HD512		
MAKE	KATO		MODEL		
SERIAL			STAMP		
HR METER	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	TIRE

ENGINE	MODEL	S/N			
Oil leakage	FAIR · Attn		Oil	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	FAIR · Attn	
Sound	FAIR · Attn		EPA	YES · NO	

CONDITION	FAIR · Attn			

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
--	---	-----------	---------------------------

COMMENT

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		
--	---	--	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。