

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/6/2	MAKE	HITACHI	MODEL	ZX30U-5B
SERIAL	HCMADHA0L00050916		STAMP	HCMADHA0L00050916	
HR METER	1163	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	300G PADS	

ENGINE : MODEL 3TNV88 **S/N** U4298

Oil leakage	<u>FAIR</u>	Attn	
Blow-By	<u>FAIR</u>	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u>	Attn	
Oil	<u>FAIR</u>	Attn	
Exhaust Color	<u>FAIR</u>	Attn	
US EPA	YES	<u>NO</u>	

MAIN PUMP

Sound	<u>FAIR</u>	Attn	
Oil leakage	<u>FAIR</u>	Attn	
Power	<u>FAIR</u>	Attn	

COOLING SYSTEM

Radiator	<u>FAIR</u>	Attn	
Oil Cooler	<u>FAIR</u>	Attn	

OPERATING SYSTEM

Swing	<u>FAIR</u>	Attn	
Travel	<u>FAIR</u>	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	<u>FAIR</u>	DIRTY
Operator's Seat	<u>FAIR</u>	Attn	破れ小 CUTS
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · <u>None</u>

BOOM / ARM / BKT

Boom	<u>FAIR</u>	Attn	
Boom Cylinder	<u>FAIR</u>	Attn	
Arm	<u>FAIR</u>	Attn	
Arm Cylinder	<u>FAIR</u>	Attn	
ATTACHMENT	<u>FAIR</u>	Attn	ガタあり LOOSE
BKT Cylinder	<u>FAIR</u>	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
シューパッド剥がれ多数あり MANY RUBBER PADS: PEELED OFF	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	YES · NO *1
BLADE	YES · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · <u>Multi</u>

COMMENT

*1 入るが「W:0051」エラー表示あり
*1 "W:0051" ERROR DISPLAY (CRANE MODE: ABLE TO TURN ON)

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。