INSPECTION SHEET 検品書

CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/6/5	MAKE	YANMAR	MODEL	C12R-B
SERIAL	27138			STAMP	27138
HR METER	1272 HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / (NONE)			SHOE	320R
TIRE					

ENGINE : MODEL 2TE67L S/N 12413		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	No. OF GEARS — GEARS
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
Swing	FAIR · Attn	
Articulate	FAIR · Attn	
FOOT BRAKE	(FAIR) · Attn	
PARKING BRAKE	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	FAIR · (Attn)	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	

MAIN FRAME		
MAIN FLAME	(FAIR) · Attn	
VESSEL		
VESSEL	(FAIR) · Attn	
REAR GATE TYPE	(NORMAL) · L-GATE (FLAT)	
REAR GATE	(FAIR) · Attn	
UNDERCARRIAGE: See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。