INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2026/5/21	MAKE	SAKAI	MODEL	T600C
SERIAL	60998			STAMP	TT1-60998
HR METER	3518 HR	Odometer	10681 km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / (CNP) / NONE			TIRE SIZE	14/70-20

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	FAIR · (Attn)	*1
PARKING BRAKE	FAIR · (Attn)	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	破れ、ガタあり A LITTLE DAMAGED, LOOSE
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
OTHERS		
Vibratory	FAIR · Attn	
Watering	FAIR · (Attn)	*2
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	(FAIR) · WORN · UNEVEN WEAR

COMMENT

*1 効かない、フルード入っていない MALFUNCTION, BRAKE FLUID: EMPTY

*2 右Rノズル欠、水漏れあり、散水不良、タイヤ散水不良、
路面散水ポンプ水漏れあり

*2 REAR RIGHT WATERING NOZZLE: MISSING, WATER LEAKING,
SPRINKLING TO ROAD & TIRES: MALFUNCTION,
WATERING PUMP FOR ROAD: WATER LEAKING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。