INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/6/9	MAKE	TCM	MODEL	808A-2
SERIAL	61307613		STAMP	S05-07613	
HR METER	1377 HR	Odometer	– km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / (CNP) / NONE		TIRE SIZE	12.5/70-16	

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	FAIR · (Attn)	ペダル固着あり PEDAL: STUCK
PARKING BRAKE	(FAIR) · Attn	
INTERIOR	**See Photos. 写真参照**	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	破れあり TORN
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
FRONT & CYLINDERS		
Arm	FAIR · (Attn)	*1
Bell crank	(FAIR) · Attn	
Bucket	FAIR · (Attn)	*2
Articulate	(FAIR) · Attn	ガタあり LOOSE

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		
TIRE WEAR	FAIR · (WORN) · UNEVEN WEAR		
COMMENT			
STEERING TYPE	(WHEEL STEERING) / COMMAND STEERING / LEVER STEERING		
RIDE CONTROL	YES · (NO)		
ATTACHMENTS			
STD BKT	(YES) · OTHER		
BLADE	YES · (NO)	Piping for Tilt	YES · (NO)
COMMENT			
*1 左シリンダーにじみあり LEFT CYLINDER: OIL OOZING			
*2 バルブ周りワイヤー切れあり、レバー不良(ワイヤー?)、バケット起こせない			
*2 WIRE AROUND VALVE: CUT, LEVER: MALFUNCTION (DUE TO CUT WIRE?), UNABLE TO RAISE THE BUCKET			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。