INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/5/29	MAKE	CAT	MODEL	953D
SERIAL	CAT0953DCLBP01442		STAMP	CAT0953DCLBP01442	
HR METER	2560 HR	SHOE	460G	YEAR	YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / (OTHER)		CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL C6.6 S/N		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	DIFF. STEERING YES · (NO)
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
BLADE & CYLINDERS		
BLADE	(FAIR) · Attn	
CYLD.(R)	(FAIR) · Attn	
CYLD.(L)	(FAIR) · Attn	
TILT CYLD	FAIR · Attn	
ANGLE CYLD	FAIR · Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	FAIR · Attn		
COMMENT			
ドーザーショベル DOZER-SHOVEL			
オルタネータ充電不良表示あり			
"E179(2)" ERROR DISPLAY FOR ALTERNATOR CHARGING			
！マーク点滅あり WARNING LAMP: BLINKED			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。