

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/6/12	MAKE	TADANO	MODEL	GR-250N-1
SERIAL No.	PLATE : FB5164		STAMP : TR256-1873		
HR METER	12778	HR	Odometer	84780	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage	FAIR <input checked="" type="radio"/> Attn *1
Blow-By	FAIR <input checked="" type="radio"/> Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn
Oil	FAIR <input checked="" type="radio"/> Attn
Exhaust Color	FAIR <input checked="" type="radio"/> Attn
OPERATION PUMP	
Sound	FAIR <input checked="" type="radio"/> Attn
Oil leakage	FAIR <input checked="" type="radio"/> Attn
Power	FAIR <input checked="" type="radio"/> Attn
COOLING SYSTEM	
Radiator	FAIR <input checked="" type="radio"/> Attn
Oil Cooler	FAIR <input checked="" type="radio"/> Attn
OPERATING SYSTEM	
Computer	OK <input checked="" type="radio"/> NG
Swing	FAIR <input checked="" type="radio"/> Attn
Travel	FAIR <input checked="" type="radio"/> Attn
TRANSMISSION	
Transmission	FAIR <input checked="" type="radio"/> Attn
No. OF GEARS	4 GEARS
4WD	4WD <input checked="" type="radio"/> 6WD
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR <input checked="" type="radio"/> DIRTY
Operator's Seat	FAIR <input checked="" type="radio"/> Attn 破れあり CUT
Glasses	FAIR <input checked="" type="radio"/> Attn
AirCon	A/C <input checked="" type="radio"/> H/C · H only · C only · None
COMMENT	

BOOM	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn 油漏れあり OIL LEAKING
JIB	YES <input checked="" type="radio"/> NO
JIB TYPE	STD <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO
FREE FALL	YES <input checked="" type="radio"/> NO
HOOK	25t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR <input checked="" type="radio"/> WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS	
OUTRIGGERS	X <input checked="" type="radio"/> H
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
COMMENT	
過巻不良、過巻解除S/W押しながら操作	
OVERWINDING PREVENTION: MALFUNCTION	
(NEED TO RELEASE THE OVERWINDING PREVENTION TO OPERATE)	
E/Gとポンプ合わせにじみあり	
CONNECTING PART BETWEEN ENGINE & PUMP: OIL OOZING	
*1 ヘッドカバー合わせ油漏れあり	
*1 ATTACHING PART OF HEAD COVER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。