

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/5/27	MAKE	CAT	MODEL	320E-2
SERIAL	CAT0320EPSXE01333		STAMP	CAT0320EPSXE01333	
HR METER	11327 / 11309	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL C6.6		S/N C8N20676	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
US EPA	<input checked="" type="radio"/> YES · NO		

MAIN PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn

COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn

OPERATING SYSTEM	
Swing	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn 若干ゴリゴリ感あり A LITTLE RATTLING
Travel	<input checked="" type="radio"/> FAIR · Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れあり TORN
Glasses	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn *1
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None

BOOM / ARM / BKT	
Boom	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn クラック、ガタあり CRACKED, LOOSE
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn
Arm	<input checked="" type="radio"/> FAIR · Attn
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn
ATTACHMENT	<input checked="" type="radio"/> FAIR · Attn ガタあり LOOSE
BKT Cylinder	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn ロッド傷あり ROD: SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

COMMENT	

BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi

COMMENT	
Hリンクガタ大 H-LINK: MUCH LOOSE	
ボディリペイントあり BODY: REPAINTED	
*1 Fひび割れ大 UPPER WINDSHIELD: MUCH CRACKED	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。