

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/5/27	MAKE	KATO	MODEL	KR-25H-V
SERIAL No.	PLATE :	0711594	STAMP :	KR255-1594	
HR METER	22521	HR	Odometer	7067	km
TIRE SIZE	16.00-25	YEAR	YR		

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATION PUMP</b>		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	<input checked="" type="radio"/> OK · NG *1	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
<b>TRANSMISSION</b>		
Transmission	<input checked="" type="radio"/> FAIR · Attn	
No. OF GEARS	4 GEARS	
4WD	<input checked="" type="radio"/> 4WD · 6WD	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	FAIR · <input checked="" type="radio"/> Attn	破れあり CUT
Glasses	FAIR · Attn	
AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None	
<b>COMMENT</b>		

<b>BOOM</b>	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn
JIB	<input checked="" type="radio"/> YES · NO
JIB TYPE	STD · <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
FREE FALL	<input checked="" type="radio"/> YES · NO
HOOK	25t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · <input checked="" type="radio"/> WORN · UNEVEN WEAR
<b>COMMENT</b>	
右前タイヤカケ大 FRONT RIGHT TIRE SHOULDER: PARTLY CHIPPED OFF	
右前ステアリングシリンダー油漏れあり FRONT RIGHT STEERING CYLINDER: OIL LEAKING	
<b>OUTRIGGERS</b>	
OUTRIGGERS	X · <input checked="" type="radio"/> H
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
<b>COMMENT</b>	
左前ステアリングシリンダーにじみあり FRONT LEFT STEERING CYLINDER: OIL Oozing	
上部左カバー損傷あり LEFT SIDE COVER OF UPPER PART: MUCH DENT	
伸縮操作切替S/W不良 (非常S/Wにて伸縮可)	
TELESCOPING SELECTOR SWITCH: MALFUNCTION	
(ABLE TO OPERATE IN THE EMERGENCY MODE)	
ブローバイホース破れあり BLOW-BY HOSE: CUT	
*1 ACS画面映り不良 ACS MONITOR: MALFUNCTION TO DISPLAY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。