

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/6/12	MAKE	KATO	MODEL	KRM-13H-II
SERIAL No.	PLATE :	5810111	STAMP :	KRC008-0111	
HR METER	24328	HR	Odometer	189401	km
TIRE SIZE	275/80R22.5	YEAR	YR		

**ENGINE : MODEL S/N**

Oil leakage	FAIR	<input checked="" type="radio"/> Attn	オイルパン油漏れあり OIL PAN: OIL LEAKING
Blow-By	<input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> Attn		
Oil	<input checked="" type="radio"/> Attn		
Exhaust Color	<input checked="" type="radio"/> Attn		

**OPERATION PUMP**

Sound	<input checked="" type="radio"/> Attn	
Oil leakage	<input checked="" type="radio"/> Attn	
Power	<input checked="" type="radio"/> Attn	

**COOLING SYSTEM**

Radiator	<input checked="" type="radio"/> Attn	
Oil Cooler	<input checked="" type="radio"/> Attn	

**OPERATING SYSTEM**

Computer	<input checked="" type="radio"/> NG	
Swing	<input checked="" type="radio"/> Attn	
Travel	<input checked="" type="radio"/> Attn	

**TRANSMISSION**

Transmission	<input checked="" type="radio"/> Attn	
No. OF GEARS	3	GEARS
4WD	<input checked="" type="radio"/> 6WD	

**INTERIOR See Photos. 写真参照**

INTERIOR COND.	CLEAN · <input checked="" type="radio"/> DIRTY
Operator's Seat	<input checked="" type="radio"/> Attn
Glasses	<input checked="" type="radio"/> Attn
AirCon	<input checked="" type="radio"/> H/C · H only · C only · None

**COMMENT**

A/C不良 A/C: MALFUNCTION
------------------------

**BOOM**

No. of Section	6	SECTIONS
CRACK/ENFORCEMENT	<input checked="" type="radio"/> Attn	
DERRICKING CYL.	<input checked="" type="radio"/> Attn	
EXTENSION CYL.	<input checked="" type="radio"/> Attn	
JIB	<input checked="" type="radio"/> NO	
JIB TYPE	STD · <input checked="" type="radio"/> PWR	
MAIN & SUB WIRE	<input checked="" type="radio"/> NO	
FREE FALL	YES · <input checked="" type="radio"/> NO	
HOOK	13t, BALL	

**UNDERCARRIAGE : See Photos. 写真参照**

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · <input checked="" type="radio"/> UNEVEN WEAR

**COMMENT**

右前サスシリンダー油漏れあり FRONT RIGHT SUSPENSION CYLINDER: OIL LEAKING
--

**OUTRIGGERS**

OUTRIGGERS	X · <input checked="" type="radio"/> H
OUTRIGGERS COND.	<input checked="" type="radio"/> Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R

**COMMENT**

左後サスカウンターバランス油漏れあり REAR LEFT SUSPENSION COUNTERBALANCE PART: OIL LEAKING
---

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。