

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/6/8	CATEGORY	木材破砕機 WOOD HOG		
MAKE	MORBARK		MODEL	3800	
SERIAL	NOT FOUND		STAMP	189-1132	
HR METER	7203	HR	Odometer	-	km
				YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP		<input checked="" type="radio"/> NONE	SHOE	TIRE
					385/65R22.5

ENGINE	MODEL C18	S/N	WRH05357	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	Oil	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
Sound	<input checked="" type="radio"/> FAIR · Attn	EPA	<input checked="" type="radio"/> YES · NO	

CONDITION	<input checked="" type="radio"/> FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	TIRE WEAR	<input checked="" type="radio"/> FAIR	WORN · UNEVEN WEAR
--	---	-----------	---------------------------------------	--------------------

COMMENT

付属品: リモコン REMOTE CONTROL AS SPARE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。