

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/6/3	MAKE	CAT	MODEL	312C
SERIAL	CAT0312CECAE03170		STAMP	CAT0312CECAE03170	
HR METER	8207	HR	YEAR	2005	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · <input checked="" type="radio"/> Attn	油汚れ大 MUCH OIL STAINS
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	<input checked="" type="radio"/> YES · NO	
MAIN PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	FAIR · <input checked="" type="radio"/> Attn *1	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · <input checked="" type="radio"/> DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れ大 MUCH TORN
Glasses	FAIR · <input checked="" type="radio"/> Attn *2	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	<input checked="" type="radio"/> FAIR · Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn	
Arm	<input checked="" type="radio"/> FAIR · Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn	
ATTACHMENT	<input checked="" type="radio"/> FAIR · Attn	ガタあり LOOSE
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
両側スプロケット摩耗あり SPROCKETS: WORN	
両側ピンブッシュ割れ多数あり MANY PIN BUSHES: BROKEN	
A/Cベルト欠、A/C点けるとCAB内から異音あり	
A/C: NO BELT, NOISES IN CAB DURING A/C WORKING	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	<input checked="" type="radio"/> YES · NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi *3
COMMENT	
ボディへコミ多数あり BODY: DEFORMED	
コントロールバルブ付近からシューシュー音あり	
AROUND CONTROL VALVE: NOISES LIKE HISSING SOUNDS	
*1 走行中速度落ちるがブームなど上物操作すると元の速度に戻る	
*1 TRAVEL SPEED: SLOWING DOWN,	
ABLE TO RETURN TO NORMAL SPEED	
AFTER OPERATING SOME IMPLEMENT	
*2 Fひび割れあり、ドア上1枚欠、ドア下アクリル板	
*2 UPPER WINDSHIELD: CRACKED,	
SOME UPPER DOOR GLASS: MISSING,	
LOWER DOOR GLASS: ACRYLIC BOARD	
*3 メクラ欠 NO CAPS	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。