

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/6/8	MAKE	KOBELCO	MODEL	7090-1F
SERIAL No.	PLATE : GK04-03264		STAMP	GK04-03264	
HR METER	21196	HR	SHOE	900FLAT	YEAR YR

ENGINE : MODEL S/N	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn *1
BOOM	
MAIN BOOM	TOP, BOTTOM, 9m × 3, 3m × 2
BOOM TOTAL	47m
TOP SHEAVE	<input checked="" type="radio"/> YES · NO
JIB	
TOWER	

INTERIOR See Photos. 写真参照	
INTERIOR COND.	<input checked="" type="radio"/> CLEAN · FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
WEIGHT	5
HOOK	90t, 50t, 35t, LIGHT HOOK × 2 (軽量フック)
FREE FALL	<input checked="" type="radio"/> YES · NO
LIFTER	<input checked="" type="radio"/> YES · NO
COMMENT	
第3ドラム付 W/3rd DRUM	
*1 走行レバー左右逆 RIGHT & LEFT TRAVEL LEVERS: REVERCED	
@NARITA YARD	
BOOM: TOP, BOTTOM, 9m × 1	
@SAKURA YARD	
BOOM: 9m × 2, 3m × 2	
HOOK: 50t, 35t, LIGHT HOOK × 2	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。