

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2026/6/9	MAKE	IHI	MODEL	CCH650
SERIAL No.	PLATE : HY38	STAMP		HY38	
HR METER	UNKNOWN	HR	SHOE	760FLAT	YEAR YR

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR · <input checked="" type="radio"/> Attn	*1
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
<b>OPERATION PUMP</b>		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK · NG	*2
Swing	FAIR · Attn	
Travel	FAIR · Attn	
<b>BOOM</b>		
MAIN BOOM	TOP, BOTTOM, 6m × 3, 3m × 1	
BOOM TOTAL	33m	
TOP SHEAVE	YES · NO	
JIB		
TOWER		

<b>INTERIOR</b>		<b>See Photos. 写真参照</b>
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり A LITTLE DAMAGED
Glasses	FAIR · Attn	
AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None	
<b>UNDERCARRIAGE : See Photos. 写真参照</b>		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
<b>COMMENT</b>		
キャタタるみあり TRACK LINKS: WORN		
WEIGHT	3	
HOOK	65t, 35t, 15/13t, BALL	
FREE FALL	<input checked="" type="radio"/> YES · NO	
LIFTER	YES · <input checked="" type="radio"/> NO	
<b>COMMENT</b>		
*1 E/Gとパワーデバイダーの間E/Gオイル漏れあり		
*1 PART BETWEEN ENGINE & POWER DIVIDER: ENGINE OIL LEAKING		
*2 未確認、MLモニター映らない NOT CHECKED, MONITOR: NOT DISPLAYING		
@NARITA YARD		
BOOM: TOP, BOTTOM, 6m × 1		
@YOTSUKAIDO YARD		
BOOM: 6m × 2, 3m × 1		
HOOK: 65t, 15/13t, BALL		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。