

INSPECTION SHEET 検品書
CRAWLER DRILL クローラドリル

INSPECTION DATE	2026/6/4	MAKE	FURUKAWA	MODEL	HCR900-DSV
SERIAL	1760500116		STAMP	1760500116	
HR METER	ERROR	HR	YEAR	YR	
CAB/CNP	CAB /	CNP /	NONE	SHOE	300G
DRIFTER MODEL	HD712				

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR · DIRTY
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C	H/C · H only · C only · None
DRIFTER HYDR.		
Lift	FAIR · Attn	*1
Swing	FAIR · Attn	シリンダーサビあり CYLINDER: RUSTY
Tilt	FAIR · Attn	シリンダーサビあり CYLINDER: RUSTY
Slide	FAIR · Attn	シリンダーサビあり CYLINDER: RUSTY

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
Guide(Slide Length)	1500 mm
Rod Changer	YES · NO
Drifter	YES · NO
Compressor	YES · NO
Blow	YES · NO
COMMENT	
左オシレーションシリンダーサビあり	
LEFT OSCILLATION CYLINDER: RUSTY	
リペイントあり REPAINTED	
ドリフタ周りホースひび割れあり SOME HOSE AROUND DRIFTER: CRACKED	
チェックランプ点灯多数、ブザー音あり	
MANY CHECK LAMPS & WARNING SOUNDS: ON	
A/C電源入らない A/C: UNABLE TO TURN ON	
停止「トルク燃料を下げる条件がある」表示あり	
MESSAGE DISPLAY FOR SUPER ECONOMY MODE PLUS	
*1 ブームシリンダーにじみ、サビあり	
*1 BOOM CYLINDER: OIL OOZING, RUSTY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。